Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	25176425	@ad<="20031216" or @rlad<="20031216" or @ptad<="20031216" or @pt1d<="20031216" or @pt3d<="20031216"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 11:04
L2	5128	(vin (vehicl\$4 near3 (manufacture id model identif\$4 identit\$4))) same (application sofware firmware program version)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 11:05
L3	264	(vin (vehicl\$4 near3 (manufacture id model identif\$4 identit\$4))) same (application sofware firmware program version) near7 (download\$4 upload\$4 load\$4 transfer\$4 updat\$4 upgrad\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 11:19
L4	240	1 and 3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 11:06
L5	5	(vin (vehicl\$4 near3 (manufacture id model identif\$4 identit\$4))) same (application sofware firmware program version) near7 (download\$4 upload\$4 load\$4 transfer\$4 updat\$4 upgrad\$4) with interfac\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 12:01
L6	2	"20050130723"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 11:30
L8	15	telematic\$4 same ((application sofware firmware program version) near7 (download\$4 upload\$4 load\$4 transfer\$4 updat\$4 upgrad\$4) near7 (portable mobile cellular handheld hand?held ((wireless radio remote\$2 wireless communication) near3 (terminal\$4 device\$4)) \$phone (personal near3 digital) pda (mobile adj station) (user near2 equipment)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 12:11
L9	12	1 and 8	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 12:03

		EAST Scare				
L10	11	telematic\$4 same ((application featur\$4 sofware firmware program version) near7 (download\$4 upload\$4 load\$4 transfer\$4 updat\$4 upgrad\$4)) near7 capab\$7	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 12:13
L11	2	"20030231550"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 14:54
S1	2	"20030096641"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 14:54
S2	25173256	@ad<="20031216" or @rlad<="20031216" or @ptad<="20031216" or @pt1d<="20031216" or @pt3d<="20031216"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 11:04
S3	3	vehicl\$4 with telematic\$4 with (dock\$4 adapt\$4 cradl\$4) with (download\$4 upload\$4 updat\$)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 15:43
S4	23	vehicl\$4 same telematic\$4 same (dock\$4 adapt\$4 cradl\$4) same (download\$4 upload\$4 updat\$)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 15:51
S5	19	S2 and S4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 15:43
S6	85	vehicl\$4 with telematic\$4 with (dock\$4 adapt\$4 cradl\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 16:59
S7	75	S2 and S6	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 16:13
S8	2	"20030060159"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 16:13

S9	2	vehicl\$4 same telematic\$4 same (dock\$4 adapter cradl\$4 (base	US-PGPUB; USPAT;	OR	ON	2006/04/03 17:05
		near2 unit)) same (vin (vehicl\$4 near3 (id model identif\$4 identit\$4))) same (locat\$4 position\$4 area geopgraphic\$4)	EPO; JPO; DERWENT; IBM_TDB			
S10	0	vehicl\$4 same (dock\$4 adapter cradl\$4 (base near2 unit)) same (vin (vehicl\$4 near3 (id model identif\$4 identit\$4))) same ((updat\$4 download\$4 upload\$4 upgrad\$4) near3 (application sofware firmware program version))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 17:08
S11	30	vehicl\$4 same (vin (vehicl\$4 near3 (id model identif\$4 identit\$4))) and ((updat\$4 download\$4 upload\$4 upgrad\$4) near3 (application sofware firmware program version)) same (dock\$4 adapter cradl\$4 (base near2 unit))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 17:08
S12	35	vehicl\$4 same (vin (vehicl\$4 near3 (id model identif\$4 identit\$4))) and ((updat\$4 download\$4 upload\$4 upgrad\$4) near6 (application sofware firmware program version)) same (dock\$4 adapter cradl\$4 (base near2 unit))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 18:59
S13	34	S2 and S12	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 17:09
S14	0	(vin (vehicl\$4 near3 (id model identif\$4 identit\$4))) same ((updat\$4 download\$4 upload\$4 upgrad\$4) near6 (application sofware firmware program version)) same (dock\$4 adapter cradl\$4 (base near2 unit))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 19:00
S15	66	(vin (vehicl\$4 near3 (id model identif\$4 identit\$4))) same (application sofware firmware program version) same (dock\$4 adapter cradl\$4 (base near2 unit))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/04 11:04
S16	25173256	@ad<="20031216" or @rlad<="20031216" or @ptad<="20031216" or @pt1d<="20031216" or @pt3d<="20031216"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/04/03 19:01

S17	61	S15 and S16	US-PGPUB; USPAT; EPO; JPO; DERWENT;	OR	ON	2006/04/03 19:01
			IBM_TDB	!	•	